
calib frame 2kx2k
Daytime Tasks
• dome flats
• bad pixel masks
Quality Control
raw data frame 2kx2k
DAS
raw data
• linearity correction
• reset correction
IDE disk
• ship to CASU
• ndf to fit
• header checking
• data verification
• pipeline processing